Timeline taken off scanner by and in Chicago Spirit of Norfolk – Fire 6/7/2022 1211 report came in of vessel fire SON Victory Rover heading to town pier park with pax **EST** 1304- Fire still active 1304- 3 crew on board boat 13 all crew off SON - 106 POB 1327- still pouring water on vessel - call to monitor drafts 1339- 7' draft STBD stern ; 6' draft STBD bow - 7'6" draft P qtr- port list visible 1342- access via ladder from fire truck as no gangway avail 1343- Reports Capt & 1 crew (CJ) stayed w/ vessel over to Pier 4 1356- 7.5' draft STBD- gone down 6" in 18mins 1356- NO one on vessel fighting fire; est. hose line from NAVY 1405- Looking for heat signatures 1410- ER point of access questions from strike team- Fire Control asking Vessel Capt 1411- Plenty of responding fire crew in area 1415 - Q of dropping fire extinguishment agent through hatch 1420 - recon team is OFF Vessel 1434- Drafts- 9' Port Stern: down 18" in 38mins 1437 - Looking to make reentry to vessel 1450- Conditions changing; dark black smoke port side 1452- looking to use crew – 2 in ; 2 out – disregard, use ALL crew 1455- Backing out of vessel; still no water supply line established 1456 - charging foam line 1458- vessel has serious; hard learn to PORT 1458 - Calls for strike team to evacuate vessel 1459 – Strike Team – MAYDAY, MAYDAY, MAYDAY 1501- ENG 12 has evacuated locating to fantail; evacuating FAST 1503- Red team move in; ENG 12 moving to vessel top floor 1503- all members of ENG 12 are accounted for 1504 – Calls from fire control to get everyone off vessel ASAP! 1505- all units evacuate immediately 1506- ENG 12 second deck, 4 people 1523- Looking at side shell heat temps on STBD side- trying to identify source & size of fire 1525 - Check for heat signatures port side 1527 – Heat signatures identified at waterline inside vessel 1528 - 200 degrees below main deck centerline 1528 - ONLY cool exterior of hull - NO water inside vessel 1531 - No more water onto vessel; only cool exterior-hopefully it will extinguish itself 1616- looking for heat on Port side and check draft marks

CG 066

1521- 91 degrees port side

No part of a report of a marine casualty investigation shall be admissible as evidence in any civil or administrative proceeding, other than an administrative proceeding initiated by the United States. 46 U.S.C. §6308.

1621- port side stern 9' draft; bow 7'

1622 – Heavy smoke Port side

1626- Starting to reignite; request main line

1708- Some firefighting boats being released in the event they need to be called back overnight.