Subject	Affiliation	Witness Topics
LCDR Kate Newkirk	Sector VA CID/Inspections	<ul> <li>Background, training and qualifications related to role at Sector Inspections</li> <li>Notification of deficiencies, emails and other communications related to the May coolant leak on the SPIRIT OF NORFOLK (SON)</li> <li>Activity &amp; observations clearing SON engineering issues related to Port MDE</li> <li>Activity conducted on scene at Navy Base Pier 4</li> </ul>
Mr. Chris O'Neal	Sector VA MITO	<ul> <li>Inspectionsbackground, training program at SEC VA, and inspector qualification process</li> <li>SON Tiered Inspection Program and Inspection/ deficiency issuance process</li> <li>Activity &amp; observations during SON Annual COI Inspection</li> <li>Vessel movement control restrictions during period the SON was limited to one engine via tug escort</li> </ul>
Captain Brandon Peter	VICTORY ROVER	<ul> <li>General account of the notification of emergency and plan and execution of the evacuation of passengers from the SON</li> <li>Background and training, re: mass evacuation drills or exercises</li> </ul>
LCDR Sarah Pulliam	Sector VA SCC Chief - SMC	<ul> <li>Search and Rescue (SAR) response and SAR Mission Coordinator (SMC) responsibilities</li> <li>Sector Command Center(SCC)responsibility during incident June 7, 2022 (SCC Chief)</li> <li>Safety Zones, Radio Marine Safety Bulletin's, and SCC response to SPAR LYRA Propulsion/Steering loss</li> <li>Transition from SAR to Fire Incident/Unified Command activities</li> <li>Passenger accountability, mass rescue, firefighting policy</li> </ul>
Mr. Jason Sleeth	Passenger	<ul> <li>Experience as a passenger on the SON during the fire on June 7, 2022</li> <li>Interactions with crew and hospitality/crew staff on board the SON</li> <li>Experience during/after evacuation on the VICTORY ROVER</li> </ul>
Mr. Bill Burket	Virginia Port Authority MIRT	<ul> <li>History and purposes of Port of Virginia Maritime Incident Response Team (MIRT)</li> <li>MIRT firefighting training and command training courses</li> <li>Mass evacuation training conducted on the SON at one time</li> <li>Account of his activities on the accident day</li> <li>Observations and assessment of the overall fire plan including recon and foam attack vessel during the mid-afternoon of June 7<sup>th</sup>, 2022</li> </ul>

CAPT Jennifer Stockwell	Sector Deputy Commander	<ul> <li>Background on the Officer in Charge Marine Inspection/Sector Commander duties including potential impact of transition to becoming the new Sector Commander</li> <li>CG firefighting expertise and applicable regulatory requirements</li> <li>Activities during the accident day and following days</li> <li>Concerns for SON stability issues</li> <li>Unified Command decisions/meetings</li> </ul>
Mr. Stephen Hanna	Bay Diesel mechanic	<ul> <li>Background, training, history w/ Bay Diesel</li> <li>Bay Diesel construct, processes and procedures</li> <li>History w/ SON</li> <li>Work completed on the Port Main Diesel Engine (MDE) from May 15-May 26</li> <li>Details of recommendation to replace the inboard turbocharger on the port main engine</li> <li>Interactions/ progress reports/ recommendations made to/with SON/ USCG</li> </ul>
Mr. Charlie Wyatt	Bay Diesel mechanic	<ul> <li>Background, training, history w/ Bay Diesel</li> <li>Bay Diesel construct, processes and procedures</li> <li>History w/ SON</li> <li>Work completed on the Port MDE from May 15-May 26</li> <li>Interactions/ progress reports/ recommendations made to/with SON/ USCG</li> </ul>
Captain Ryan Nadeau	Master, SPIRIT OF NORFOLK	<ul> <li>Background training and experience</li> <li>Role as Director of Marine Operations</li> <li>Description and function of the Port Safety Officer duties</li> <li>Activities related to port MDE repairs from May 15 – May 26</li> <li>Interactions with Sec VA Inspections from May 15 – May 26</li> <li>Activities related to the accident day and support to firefighting operations.</li> </ul>
Captain Larry Sullivan	ROSEMARY McCALLISTER Captain	<ul> <li>Background training and experience as tug Captain</li> <li>Deployment plans and preparation</li> <li>Activities on the accident day and responsibilities directing McAllister tugs activities.</li> <li>FF efforts, evacuation efforts, SON mooring assistance</li> <li>SPAR LYRA Loss of Propulsion/Steering during response to SONincident</li> </ul>

Mr. Scott Smith	Senior VP Hornblower Group	<ul> <li>Explanation of Hornblower (HB) City Cruises organizational structure</li> <li>SafeCruise, HB City Cruises safety/casualty reporting</li> <li>Activities on accident day and following days as Responsible Party for HB</li> <li>Actual status of the SPIRIT OF NORFOLK as of Oct 27, 2022 (re: total constructive loss?)</li> </ul>
Mr. Ken Edgar	Don Jon Smit Salvage	<ul> <li>Background and experience related to firefighting and salvage operations</li> <li>Activities on accident day and following days to include:</li> <li>Activation to incident</li> <li>Interactions with CG Salvage Team (SERT)/Sec VA inspections staff regarding stability</li> <li>Interactions with Unified Command, Incident Command, USCG, &amp; Fire Departments on scene</li> <li>Interactions between hired Fire agency and salvage team</li> <li>Firefighting, dewatering and salvage plans and preparations</li> <li>Detrimental effect of a known port list on the SON</li> </ul>
Mr. Bryan Bracey	Senior Deckhand SPIRIT OF NORFOLK	<ul> <li>Background as crew on the SON</li> <li>Activities on May 15/coolant leak "steam"</li> <li>Follow up investigation for the May 15 incident and interview by the HB Norfolk Port Safety Officer</li> <li>Activities on the accident day</li> </ul>
Ms. Jolene Price- Thompson	City Cruises GM	<ul> <li>Role as City Cruises General Manager and organizational structure</li> <li>Role as supervisor of Captain Nadeau</li> <li>Communications about port MDE overhaul/repair</li> <li>Activities related to accident day and role of Responsible Party for Hornblower at Unified Command</li> </ul>
Mr. Tim Brown	CG Regulations	<ul> <li>The regulatory process followed by the CG and other federal agencies</li> <li>Applicable regulatory scheme covering the SPIRIT OF NORFOLK, old "K"</li> <li>Explanation of the creation of a safety regulation from concept to publication</li> <li>"Grandfathering", explanation of the reasons and concerns</li> <li>Role of Public Comments and economic impacts on rulemaking</li> </ul>
LCDR Jonathan Duffett	CG Compliance Policy SME	<ul> <li>Objective of CG oversight on small passenger vessels</li> <li>General overview of lines of authority from Officer in Charge, Marine Inspection to Marine Inspector with explanation of each role</li> <li>Equivalent safety measure in vessels with propulsion casualty</li> <li>Objective of Tiered inspection system and impact on marine inspections and qualifications of Marine Inspectors</li> <li>Use of a CG 835 and applicability to engine issues. Role of Marine Inspector in clearing deficiencies and role of industry representatives in providing proof to CG Marine Inspectors</li> <li>General Fire protection</li> </ul>

Mr. Charles Walther	Mechanical Systems SME	<ul> <li>SME background/ history and experience relating to marine engines and associated equipment</li> <li>Layup and removal from procedures/ recommendations</li> <li>High speed vs. low-speed usage of marine diesel engine (engine was previously used as a generator)</li> <li>Basic engineering Casualty control procedures on the marine engine room equipment</li> <li>Post casualty troubleshooting procedures on marine engine room equipment</li> <li>Providing recommendations for repairs and or replacement of engine room components</li> </ul>
CAPT Samson Stevens	Sector Commander	<ul> <li>Background on the Officer in Charge, Marine Inspection/Sector Commander duties</li> <li>Activities for accident and following days</li> <li>Interactions with on scene fire fighters, Unified Command, Responsible Party, and USCG members</li> <li>Unified Command decisions/meetings</li> </ul>
Ms. Candace Baker	Restaurant Manager SON	<ul> <li>Training and responsibilities associated with Restaurant Manager</li> <li>Position requirements</li> <li>Passenger safety demonstrations and announcements</li> <li>Crew/wait staff/passenger interactions during/after fire detection on June 7, 2022</li> <li>Crew/wait staff/passenger interactions during evacuation</li> </ul>
Mr. Justin Wagner	Passenger VICTORY ROVER	<ul> <li>Experience as a passenger on the VICTORY ROVER during the passenger evacuation on June 7, 2022</li> <li>Interactions with crew as the VICTORY ROVER prepared for evacuating personnel from the SON</li> <li>Narration of the sequence of stills and videos that comprise CG Exhibit 073</li> </ul>
Mr. Robert Enloe	"Chief Mate" SON	<ul> <li>Role in carrying out preventative maintenance as lead on SON</li> <li>Maintenance of the SON hydraulic system</li> <li>Discrepancies in Vessel Vanguard PM Tracking 12/21 onwards, reasons and work arounds</li> <li>As a result of the engine rebuild what was he told regarding the turbo inspection and monitoring for the turbo that needed replacement.</li> </ul>
Mr. Brian Vaughn	ATF Report Cause and Origin	<ul> <li>Role in investigating fire cause and origin</li> <li>USCG/ATF Memo of Understanding</li> <li>Investigationand results of SPIRIT OF NORFOLK post fire and forensic analysis directly related to the fire's cause and origin</li> </ul>
Mr. Jeremiah Perry	Crew SON	<ul> <li>Role as senior deckhand</li> <li>Training as crew on the vessel</li> <li>Actions and observations while aboard the vessels on the accident voyage and other dates</li> </ul>