


No part of a report of a marine casualty investigation shall be admissible as evidence in any civil or administrative proceeding, other than an administrative proceeding initiated by the United States. 46 U.S.C. §6308.

Hydraulic Steering Pipe Located on the Port side of Engine Room



Source: Bay Diesel



Source: USCG



Source: NTSB



Source: USCG

Hydraulic Steering Pipe Located Along Bulkhead in Hydraulic Area of Engine Room



Source: USCG Source: Castlerock




Source: USCG

No part of a report of a marine casualty investigation shall be admissible as evidence in any civil or administrative proceeding, other than an administrative proceeding initiated by the United States. 46 U.S.C. §6308.

Hydraulic Pump Hose Located in the Hydraulic Area of the Engine Room







Source: Castlerock



Source: USCG

Hydraulic System Pressure Relief Valve





Source: Castlerock





Source: USCG