

Main Deck After Window Mentioned By Captain Nadeau To Firefighters

Engine Room Escape Hatch

Main Deck Aft Starboard Side

Engine Room Watertight Door In Red Highlight Box

Looking Aft From The Galley



No part of a report of a marine casualty investigation shall be admissible as evidence in any civi or administrative proceeding, other than an administrative proceeding initiated by the United

States. 46 U.S.C. §6308.



Figure 58: View towards starboard aft main cabin



Top Left, Image taken on June 6, 2022, during survey of the SPIRIT OF NORFOLK and included in Castlerock Survey Report.




Left,
Apparent
placard for
the engine
room
emergency
escape

Bottom Left,

Engine Room Escape Hatch

Main Deck Aft Starboard Side

No part of a report of a marine casualty investigation shall be admissible as evidence in any civil or administrative proceeding, other than an administrative proceeding initiated by the United States. 46 U.S.C. §6308.



Left,

Seating chart for June 7th, 2022, accident voyage cruise.

Bottom Left,
Notation regarding
engine room escape
hatch on seating